

DAMAGE REPORT

Inbound carrier: AS NINA


ASNI420S 420S

19-May-2024 11:20

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCKU6406831 | DENT | RIGHT |
| TCKU6406831 | BENT | LEFT |
| TCKU7480129 | DENT | RIGHT |
| MAGU2123816 | DENT | FRONT |
| MAGU2123816 | DENT | RIGHT |
| MSKU0437017 | DENT | LEFT |
| MSKU0282342 | BENT | LEFT |
| MSKU0282342 | DENT | FLOOR |
| SUDU1373923 | BENT | RIGHT |
| CAIU6292982 | BENT | RIGHT |
| MSKU7642862 | BENT | LEFT |
| MSKU7642862 | DENT | TOPROOF |
| MRKU3820820 | BENT | RIGHT |
| HASU1463114 | BENT | LEFT |
| TCLU2474645 | DENT | CORNERPOST |
| TGHU4819914 | BENT | LEFT |
| TCKU1719896 | BENT | LEFT |
| MRSU5960320 | DENT | FLOOR |
| MRSU5960320 | BENT | RIGHT |
| MRKU8728974 | BENT | LEFT |
| TRLU9706926 | BENT | LEFT |
| MRKU2835039 | BENT | LEFT |
| MRKU2241309 | DENT | FLOOR |
| MRKU2241309 | DENT | RIGHT |
| MRKU4393867 | BENT | LEFT |
| MRSU3093195 | BENT | RIGHT |
| TRHU8173742 | DENT | RIGHT |
| MRKU2877564 | DENT | FLOOR |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| SEGU7317974 | CUT | TARPAULIN |
| PONU7794470 | BENT | LEFT |
| MRKU4302717 | BENT | RIGHT |
| MSKU7321184 | DENT | RIGHT |
| MSKU7321184 | BENT | LEFT |
| MSKU5694039 | BENT | LEFT |
| MSKU3108191 | TORN | BACK |
| MSKU3108191 | TORN | DOORSYSTEM |
| MVIU2004253 | BENT | RIGHT |
| MRKU4330447 | DENT | RIGHT |
| MRKU4330447 | DENT | LEFT |
| TGBU6645790 | CUT | TOPROOF |
| MNBU3706709 | SCRATCHED | LEFT |
| TCNU2438500 | BENT | RIGHT |
| TCNU2438500 | BENT | LEFT |
| MRSU3290342 | BENT | RIGHT |
| MRSU3375199 | DENT | FLOOR |
| MRSU3375199 | BENT | RIGHT |
| MSKU6612349 | DENT | RIGHT |
| MSKU6612349 | DENT | FLOOR |
| MRKU9333475 | BENT | RIGHT |
| MRKU9333475 | BENT | LEFT |
| MRKU7671663 | DENT | RIGHT |
| MRKU1102994 | DENT | LEFT |
| MRKU6186323 | BENT | LEFT |
| MRKU6186323 | DENT | FLOOR |
| MAEU4067782 | CUT | TOPROOF |
| MRSU3564058 | BENT | RIGHT |
| MRSU3564058 | BENT | LEFT |
| MRKU2540866 | DENT | LEFT |
| MRSU5952936 | DENT | LEFT |
| MRKU4484627 | BENT | LEFT |
| SUDU7607356 | HOLE | TOPROOF |
| MSKU9700715 | IMO LABEL | RIGHT |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department

AS NINA
9401178
Page 2 of 9

| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| MSKU9700715 | IMO LABEL | LEFT |
| MRKU3634640 | DENT | RIGHT |
| MRKU0591524 | DENT | LEFT |
| MRSU5391877 | DENT | RIGHT |
| MRSU5391877 | DENT | LEFT |
| SUDU6006746 | DENT | RIGHT |
| MRKU3789160 | DENT | RIGHT |
| FSCU8289780 | DENT | RIGHT |
| MSKU7023549 | DENT | LEFT |
| MRSU5165294 | BENT | RIGHT |
| CAAU6563356 | DENT | RIGHT |
| MRSU3417057 | BENT | RIGHT |
| BMOU2475286 | DENT | LEFT |
| MRKU7020379 | BENT | RIGHT |
| MRKU7020379 | BENT | LEFT |
| SJKU2414810 | CUT | TARPAULIN |
| SUDU8529005 | BENT | LEFT |
| MSKU5268727 | DENT | RIGHT |
| SUDU7826708 | BENT | RIGHT |
| TCLU9215081 | DENT | LEFT |
| PONU0043517 | DENT | LEFT |
| PONU0043517 | BENT | FRONT |
| MRSU4317258 | BENT | RIGHT |
| MSKU0308724 | BENT | RIGHT |
| MSKU1055404 | BENT | LEFT |
| MSKU8600938 | BENT | LEFT |
| MRKU2339105 | BENT | LEFT |
| MSKU0310721 | BENT | RIGHT |
| TGHU8393956 | DENT | RIGHT |
| TGHU8393956 | BENT | LEFT |
| PONU8171582 | BENT | LEFT |
| HASU5118116 | DENT | LEFT |
| MRKU7300847 | DENT | FRONT |
| MRKU8935082 | BENT | LEFT |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*


Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCKU1819513 | BENT | FRONT |
| TCKU1819513 | DENT | CORNERPOST |
| MRSU5226553 | DENT | RIGHT |
| SUDU8653802 | BENT | DOORSYSTEM |
| SUDU8653802 | DENT | CORNERPOST |
| MSKU9859306 | BENT | RIGHT |
| MRKU9281387 | BENT | RIGHT |
| MRKU9281387 | BENT | LEFT |
| MRKU7316360 | BENT | RIGHT |
| MRKU7316360 | BENT | LEFT |
| TCLU3406603 | BENT | LEFT |
| MSKU9357740 | DENT | RIGHT |
| MRSU4523351 | DENT | RIGHT |
| MRKU5912041 | DENT | LEFT |
| MRKU7934306 | DENT | LEFT |
| MRKU7642074 | BENT | RIGHT |
| MRKU7642074 | BENT | CORNER |
| CIPU5200354 | CUT | LEFT |
| CAIU8182670 | DENT | RIGHT |
| MSKU1066923 | DENT | RIGHT |
| MRKU9293644 | DENT | LEFT |
| SJKU2416915 | BENT | RIGHT |
| MNBU3384346 | BENT | RIGHT |
| MNBU3384346 | BENT | TARPAULIN |
| MRKU2547829 | DENT | RIGHT |
| GCXU5716304 | DENT | LEFT |
| SUDU8647137 | TORN | DOORSYSTEM |
| MSKU7850505 | DENT | FRONT |
| MSKU7850505 | CRACK | FRONT |
| SJKU2415375 | CUT | TARPAULIN |
| MSKU5695565 | BENT | DOORSYSTEM |
| SUDU8054620 | BENT | LEFT |
| MRKU8986095 | DENT | RIGHT |
| MSKU2781084 | DENT | LEFT |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*


Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCNU2746761 | DENT | LEFT |
| MSKU1516023 | DENT | LEFT |
| MSKU0565609 | CUT | BOTTOM |
| MSKU0565609 | CUT | FLOOR |
| SUDU5970824 | DENT | LEFT |
| HASU1317300 | BENT | LEFT |
| TCNU2482437 | DENT | LEFT |
| MAEU4211098 | CUT | TARPAULIN |
| MRKU5949415 | BENT | LEFT |
| TEMU6143597 | BENT | LEFT |
| MRKU9877268 | BENT | RIGHT |
| MRSU5460582 | BENT | LEFT |
| MRKU5872118 | BENT | LEFT |
| MRKU0466348 | DENT | LEFT |
| PONU1915039 | DENT | FLOOR |
| SUDU5327799 | BENT | LEFT |
| MRKU2994832 | BENT | RIGHT |
| TCKU1130524 | BENT | RIGHT |
| TCKU1130524 | BENT | LEFT |
| MNBU3520566 | SCRATCHED | RIGHT |
| MRSU4871589 | DENT | CORNERPOST |
| HASU4052544 | DENT | LEFT |
| MRSU6537441 | BENT | LEFT |
| FCIU4149179 | BENT | FRONT |
| MSKU1591855 | BENT | LEFT |
| MSKU1591855 | DENT | CORNERPOST |
| SJKU2414785 | CUT | TARPAULIN |
| TLLU5974787 | DENT | FRONT |
| TCKU2143526 | BENT | LEFT |
| MAEU4687926 | CUT | TARPAULIN |
| SUDU8868760 | DENT | LEFT |
| PONU7819177 | BENT | RIGHT |
| PONU7819177 | DENT | LEFT |
| MRKU5028529 | BENT | LEFT |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TCKU7759345 | IMO LABEL | RIGHT |
| TCKU7759345 | IMO LABEL | BACK |
| TCKU7759345 | IMO LABEL | LEFT |
| TRHU4055510 | DENT | LEFT |
| SUDU8787329 | DENT | RIGHT |
| MRSU4330434 | DENT | LEFT |
| TLLU5873652 | DENT | RIGHT |
| GCXU5576711 | DENT | RIGHT |
| MSKU1472115 | IMO LABEL | RIGHT |
| MSKU1472115 | IMO LABEL | LEFT |
| MRKU6353077 | DENT | RIGHT |
| MSKU0890492 | DENT | LEFT |
| HASU4342245 | DENT | RIGHT |
| HASU4185871 | DENT | RIGHT |
| HASU4185871 | DENT | LEFT |
| CAAU5535977 | DENT | RIGHT |
| CAAU5535977 | DENT | LEFT |
| MRKU9953584 | DENT | LEFT |
| TGHU2656973 | BENT | LEFT |
| MRKU4916253 | SCRATCHED | CORNER |
| MRKU5124179 | DENT | RIGHT |
| MSKU4086230 | CUT | FRONT |
| MRKU5450154 | BENT | RIGHT |
| SUDU8527110 | BENT | RIGHT |
| MSKU2932299 | BENT | RIGHT |
| MRKU5360317 | BENT | LEFT |
| CAIU4730246 | DENT | LEFT |
| UETU2072526 | BENT | LEFT |
| MRKU1026580 | DENT | LEFT |
| MRKU1026580 | DENT | RIGHT |
| MRKU1026580 | DENT | CORNERPOST |
| MSKU7178089 | BENT | RIGHT |
| MSKU7178089 | BENT | LEFT |
| MRKU1027695 | DENT | FLOOR |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| MRKU1027695 | BENT | LEFT |
| MRKU0559585 | BENT | RIGHT |
| MRKU0559585 | DENT | RIGHT |
| MRKU0559585 | BENT | DOORSYSTEM |
| TCNU1094566 | DENT | RIGHT |
| TCNU1094566 | BENT | LEFT |
| TCNU1094566 | HOLE | LEFT |
| MRKU0152060 | DENT | FLOOR |
| MSKU3206069 | CUT | DOOR |
| MIEU3012035 | BENT | RIGHT |
| FCIU8042471 | BENT | LEFT |
| MIEU2032206 | DENT | FLOOR |
| MIEU2032206 | BENT | LEFT |
| MRKU3999382 | DENT | LEFT |
| MRKU8926199 | BENT | LEFT |
| MRSU0103690 | BENT | RIGHT |
| GESU1055419 | DENT | RIGHT |
| MRKU8732758 | BENT | LEFT |
| MSKU5253286 | BENT | LEFT |
| MRSU0130628 | BENT | LEFT |
| MRSU0130628 | BENT | RIGHT |
| TGBU9319205 | DENT | RIGHT |
| MRKU5973031 | DENT | FLOOR |
| MSKU6368150 | BENT | LEFT |
| MSKU1227606 | BENT | LEFT |
| MSKU1227606 | BENT | RIGHT |
| MRKU8540499 | BENT | LEFT |
| MRSU4830506 | HOLE | TOPROOF |
| TEMU8349458 | BENT | LEFT |
| PONU7461519 | BENT | RIGHT |
| TCKU6788800 | BENT | LEFT |
| MRSU3770850 | DENT | LEFT |
| MSKU1997607 | CUT | TOPROOF |
| MRSU4931311 | BENT | RIGHT |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TEMU2125337 | DENT | CORNERPOST |
| MRSU3041890 | BENT | LEFT |
| MIEU3007110 | DENT | RIGHT |
| MRKU2707510 | DENT | RIGHT |
| TRHU5633295 | HOLE | TOPROOF |
| MRKU7313799 | BENT | RIGHT |
| TCKU1243876 | BENT | LEFT |
| SUDU1954635 | DENT | LEFT |
| MAEU4159913 | CUT | TARPAULIN |
| MRSU5015416 | BENT | RIGHT |
| MSKU4233264 | BENT | LEFT |
| MSKU4233264 | DENT | LEFT |
| MRKU5890641 | DENT | LEFT |
| SJKU2415420 | CUT | TARPAULIN |
| GCXU5744306 | DENT | RIGHT |
| MRKU0424023 | DENT | LEFT |
| MRKU7055230 | BENT | CORNERPOST |
| MRKU7055230 | BENT | CORNER |
| MSKU4432820 | BENT | LEFT |
| MRKU8640836 | BENT | RIGHT |
| MRKU8640836 | BENT | LEFT |
| TCKU1441531 | BENT | RIGHT |
| TCKU1441531 | BENT | LEFT |
| TTNU1143175 | BENT | RIGHT |
| TTNU1143175 | BENT | LEFT |
| TEMU5913707 | BENT | LEFT |
| MRKU2557370 | BENT | FLOOR |
| MRKU2337289 | DENT | RIGHT |
| MRKU9553870 | BENT | LEFT |
| TCLU3868520 | BENT | LEFT |
| PONU1935570 | DENT | LEFT |
| PONU1935570 | DENT | RIGHT |
| MRKU1106557 | DENT | RIGHT |
| MSKU8172676 | IMO LABEL | LEFT |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department



| Container | Damage type | Damage location |
|-------------|-------------|-----------------|
| TRHU4667984 | IMO LABEL | RIGHT |
| MSKU7307437 | BENT | RIGHT |
| MRKU0352366 | BENT | RIGHT |
| MRKU0352366 | CUT | RIGHT |
| SUDU6951726 | DENT | RIGHT |
| SUDU7463705 | BENT | RIGHT |
| FSCU8313572 | DENT | RIGHT |
| FSCU8313572 | HOLE | TOPROOF |
| TRHU4846085 | CUT | TOPROOF |
| MRKU6804400 | DENT | RIGHT |
| MRKU7289007 | DENT | BOTTOM |

*Signed for receipt only,
without prejudice of liability.
Discharged same condition as
loaded.*

Without any liability accepted
Constanta South Container Terminal
Planning Department

